L Number	Hits	Search Text	DB	Time stamp
-	1	((measur\$5 or detect\$3 or sens\$3) near3 (position or	USPAT;	2004/10/20 06:58
		location)) and (pointing adj error) and ((geometric or geometrical) adj error adj vector)	US-PGPUB	
_	1	(geometrical) adjerror adj vector) (pointing adj error) and ((geometric or geometrical) adj error	USPAT;	2004/10/19 10:20
	•	adj vector)	US-PGPUB	200 17 10/10 10:20
-	1	((geometric or geometrical) adj error adj vector)	USPAT;	2004/10/19 10:24
			US-PGPUB	
-	789	pointing adj error	USPAT;	2004/10/19 14:24
	283	((measur\$5 or detect\$3 or sens\$3) near3 (position or	US-PGPUB USPAT;	2004/10/19 10:21
•	203	location)) and (pointing adj error)	US-PGPUB	2004/10/13 10:21
-	2	((measur\$5 or detect\$3 or sens\$3) near3 (shaft or spindle or	USPAT;	2004/10/19 10:23
		axle) near3 (position or location)) and (pointing adj error)	US-PGPUB	
-	1	((measur\$5 or detect\$3 or sens\$3) near3 (shaft or spindle or	USPAT;	2004/10/19 10:23
		axle) near3 (position or location)) and (determin\$5 near3 error near3 vector) and (pointing adj error)	US-PGPUB	
_	8	(geo\$9 near3 (error adj vector))	USPAT;	2004/10/19 10:26
		(goode neare (ener day vester))	US-PGPUB	200 17 107 70 10120
-	1	((shaft or spindle or axle or axis or rotator or rotor) near3	USPAT;	2004/10/19 10:42
		(distance or range) near3 (measur\$5 or detect\$3 or sens\$3)	US-PGPUB	
		near3 (probe or sensor or tranducer or detector)) and		
		((measur\$5 or detect\$3 or sens\$3) near3 (shaft or spindle or axle or axis or rotator or rotor) near3 (position or location or		
		rotation or angle or turn)) and (determin\$5 near3 geo\$9 near3		
		(error or fault) near3 vector) and (determin\$5 near3 (pointing		
		or indicat\$3) near3 (error or fault))		
-	1	((shaft or spindle or axle or axis or rotator or rotor) near3	USPAT;	2004/10/19 10:43
		(distance or range) near3 (measur\$5 or detect\$3 or sens\$3) near3 (probe or sensor or tranducer or detector)) and	US-PGPUB	
		((measur\$5 or detect\$3 or sens\$3) near3 (shaft or spindle or		
		axle or axis or rotator or rotor) near3 (position or location or		
		rotation or angle or turn)) and (determin\$5 near3 (error or		
		fault) near3 vector) and (determin\$5 near3 (pointing or		
	3	indicat\$3) near3 (error or fault)) ((shaft or spindle or axle or axis or rotator or rotor) near3	USPAT;	2004/10/20 08:10
-	3	(distance or range) near3 (measur\$5 or detect\$3 or sens\$3)	US-PGPUB	2004/10/20 00:10
		near3 (probe or sensor or tranducer or detector)) and		(•
		((measur\$5 or detect\$3 or sens\$3) near3 (shaft or spindle or	,	
:		axle or axis or rotator or rotor) near3 (position or location or		
		rotation or angle or turn)) and (determin\$5 near3 (pointing or indicat\$3) near3 (error or fault))		
_	189	73/1.01.ccls.	USPAT;	2004/10/19 10:44
			US-PGPUB	
-	0	73/175.ccls.	USPAT;	2004/10/19 10:44
	_	72/177 este	US-PGPUB	2004/10/10 10:44
-	0	73/177.ccls.	USPAT; US-PGPUB	2004/10/19 10:44
-	0	73/178.ccls.	USPAT;	2004/10/19 10:44
			US-PGPUB	
-	154	73/179.ccls.	USPAT;	2004/10/19 10:45
	040	72/965 0 colo	US-PGPUB USPAT:	2004/10/19 10:45
-	619	73/865.9.ccls.	US-PGPUB	2004/10/18 10:45
-	632	73/866.5.ccls.	USPAT;	2004/10/19 10:45
			US-PGPUB	
-	216	73/432.1.ccls.	USPAT;	2004/10/19 10:45
	1004	701/1 colo	US-PGPUB	2004/10/10 10:45
-	1284	701/1.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
	1104	701/200.ccls.	USPAT;	2004/10/19 10:45
			US-PGPUB	
-	1114	701/207.ccls.	USPAT;	2004/10/19 10:45
	AAE	701/214 cole	US-PGPUB	2004/10/10 10:45
-	445	701/214.ccls.	USPAT; US-PGPUB	2004/10/19 10:45
-	145	701/221.ccls.	USPAT;	2004/10/19 10:46
		·	US-PGPUB	

	407	702/85.ccls.	USPAT;	2004/10/19 10:46
-	407	702/05.CCIS.	US-PGPUB	2004/10/19 10.40
-	308	702/94.ccls.	USPAT;	2004/10/19 10:46
-	190	702/95.ccls.	US-PGPUB USPAT;	2004/10/19 10:46
-	254	702/127.ccls.	US-PGPUB USPAT;	2004/10/19 10:46
-	646	702/150.ccls.	US-PGPUB USPAT; US-PGPUB	2004/10/19 10:46
-	253	702/151.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	211	702/152.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	173	702/153.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
-	53	714/699.ccls.	USPAT; US-PGPUB	2004/10/19 10:46
_	178	714/703.ccls.	USPAT; US-PGPUB	2004/10/19 10:47
-	0	702/94.ccls. and 73/1.77.ccls.	USPAT; US-PGPUB	2004/10/19 10:48
-	0	702/94.ccls. and 73/432.1.ccls.	USPAT; US-PGPUB	2004/10/19 10:48
-	0	702/94.ccls. and 701/1.ccls.	USPAT; US-PGPUB	2004/10/19 10:48
-	0	702/94.ccls. and 714/699.ccls.	USPAT; US-PGPUB	2004/10/19 10:49
-	0	702/94.ccls. and 714/703.ccls.	USPAT; US-PGPUB	2004/10/19 10:49
-	1	702/94.ccls. and 73/1.01.ccls.	USPAT; US-PGPUB	2004/10/19 10:50
-	2	702/94.ccls. and 73/1.75.ccls.	USPAT; US-PGPUB	2004/10/19 10:51
-	1	702/94.ccls. and 73/1.78.ccls.	USPAT; US-PGPUB	2004/10/19 10:52
-	10	702/94.ccls. and 73/1.79.ccls.	USPAT; US-PGPUB	2004/10/19 10:52
-	3	702/94.ccls. and 73/865.9.ccls.	USPAT; US-PGPUB	2004/10/19 10:57
-	1	702/94.ccls. and 73/866.5.ccls.	USPAT; US-PGPUB	2004/10/19 10:57
-	4	702/94.ccls. and 701/200.ccls.	USPAT; US-PGPUB	2004/10/19 10:57
-	10	702/94.ccls. and 701/207.ccls.	USPAT; US-PGPUB	2004/10/19 10:58
-	2	702/94.ccls. and 701/214.ccls.	USPAT; US-PGPUB	2004/10/19 10:58
-	6	702/94.ccls. and 701/221.ccls.	USPAT; US-PGPUB	2004/10/19 10:58
•	14	702/94.ccls. and 702/85.ccls.	USPAT; US-PGPUB USPAT;	2004/10/19 10:59
-	41	702/94.ccls. and 702/95.ccls.	US-PGPUB	2004/10/19 11:00
-	51	702/94.ccls. and 702/127.ccls. 702/94.ccls. and 702/150.ccls.	USPAT; US-PGPUB USPAT;	2004/10/19 11:02
-	51	702/94.ccls. and 702/150.ccls.	US-PGPUB USPAT;	2004/10/19 11:05
	8	702/94.ccls. and 702/151.ccls.	US-PGPUB USPAT;	2004/10/19 11:07
	7	702/94.ccls. and 702/153.ccls.	US-PGPUB USPAT;	2004/10/19 11:07
-	490	((pointing or indicat\$3) adj (error or fault)) and ((determin\$5 or	US-PGPUB USPAT;	2004/10/19 14:30
		measur\$5 or detect\$3 or sens\$3) near5 (shaft or spindle or axle or axis) near5 (position or location))	US-PGPUB	

-	1	((pointing or indicat\$3) adj (error or fault)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (shaft or spindle or axle or axis) near5 (position or location)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (geo\$9 adj (error or fault) adj vector))	USPAT; US-PGPUB	2004/10/19 14:30
-	· 1	((pointing or indicat\$3) adj (error or fault)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (shaft or spindle or axle or axis) near5 (position or location)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (geo\$9 adj (error or fault) adj vector))	EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:32
-	8	((pointing or indicat\$3) adj (error or fault)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (shaft or spindle or axle or axis) near5 (position or location))	EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:30
-	0	((pointing or indicat\$3) adj (error or fault)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (bearing) near5 (position or location)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (geo\$9 adj (error or fault) adj vector))	EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:33
•		((pointing or indicat\$3) adj (error or fault)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (bearing) near5 (position or location)) and ((determin\$5 or measur\$5 or detect\$3 or sens\$3) near5 (geo\$9 adj (error or fault) adj vector))	USPAT; US-PGPUB	2004/10/19 14:33
-	704733	((method\$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat\$5 adj (distance or range)) with (measur\$5 or determin\$5 or detect\$3 or sens\$3) with (probe or transducer or detector or sensor)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:37
-	20434	((method\$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat\$5 adj (distance or range)) with (measur\$5 or determin\$5 or detect\$3 or sens\$3) with (probe or transducer or detector or sensor))) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (shaft or spindle or axle or axis) with (position or location))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:38
-	1091	((method\$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat\$5 adj (distance or range)) with (measur\$5 or determin\$5 or detect\$3 or sens\$3) with (probe or transducer or detector or sensor))) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (shaft or spindle or axle or axis) with (position or location)) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (pointing or indicat\$3) with (error or fault))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:40
-	5	((method\$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat\$5 adj (distance or range)) with (measur\$5 or determin\$5 or detect\$3 or sens\$3) with (probe or transducer or detector or sensor))) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (shaft or spindle or axle or axis) with (position or location)) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with geo\$9 with error with vector)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:43
-	3	((method\$5 or process or procedure or step or algorithm or scheme or plan) with (distance or range or (rotat\$5 adj (distance or range)) with (measur\$5 or determin\$5 or detect\$3 or sens\$3) with (probe or transducer or detector or sensor))) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (shaft or spindle or axle or axis) with (position or location)) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with geo\$9 with error with vector) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (pointing or indicat\$3) with (error or	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:41
-	8	fault)) ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with geo\$9 with (error or fault) with vector) and ((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (pointing or indicat\$3) with (error or fault))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/19 14:44

-	61	((measur\$5 or determin\$5 or detect\$3 or sens\$3) with geo\$9 with error with vector)	USPAT; US-PGPUB; EPO; JPO;	2004/10/19 14:54
			DERWENT; IBM_TDB	
-	4078	((measur\$5 or determin\$5 or detect\$3 or sens\$3) with (shaft	USPAT;	2004/10/19 14:56
	/	or spindle or axle or axis) with (position or location or rotation)	US-PGPUB;	
		with error)	EPO; JPO; DERWENT;	
			IBM TDB	
-	904	((measur\$5 or determin\$5 or detect\$3 or sens\$3) near5 (shaft	USPAT;	2004/10/19 14:56
		or spindle or axle or axis) near5 (position or location or	US-PGPUB;	
		rotation) near5 error)	EPO; JPO; DERWENT;	
			IBM_TDB	
-	97	((measur\$5 or determin\$5 or detect\$3 or sens\$3) near5 (shaft	USPAT;	2004/10/20 08:05
	!	or spindle or axle or axis) near5 (position or location or rotation) near5 (error or fault)) and ((pointing or indicating or	US-PGPUB; EPO; JPO;	
		indication or index or arrow or needle) near5 (error or fault))	DERWENT;	
			IBM_TDB	
-	2	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near3	USPAT;	2004/10/20 07:01
		(position or location or distance) near3 (shaft or spindle or axle or axis) near3 (end or limit)) and ((pointing or indicat\$3 or	US-PGPUB; EPO; JPO;	
		index\$3) adj error) and ((geometric or geometrical) adj error	DERWENT;	
	_	adj vector)	IBM_TDB	
-	2	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near3 (position or location or distance) near3 (shaft or spindle or axle	USPAT; US-PGPUB;	2004/10/20 07:02
		or axis) near3 (end or limit)) and ((pointing or indicat\$3 or	EPO; JPO;	
		index\$3) adj error) and (error adj vector)	DERWENT;	
	_	(/	IBM_TDB	2004/40/20 07:02
•	5	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near5 (position or location or distance) near5 (shaft or spindle or axle	USPAT; US-PGPUB;	2004/10/20 07:03
		or axis) near5 (end or limit)) and ((pointing or indicat\$3 or	EPO; JPO;	
		index\$3) near3 error) and (error near3 vector)	DERWENT;	
	77	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near5	IBM_TDB USPAT;	2004/10/20 07:08
-	''	(measures of defectes of senses of determines) hears (position or location or distance) near5 (shaft or spindle or axle	US-PGPUB;	2004/10/20 07:00
		or axis)) and ((pointing or indicat\$3 or index\$3) near3 error)	EPO; JPO;	
li .		and (error near3 vector)	DERWENT; IBM TDB	
_	1	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near5	USPAT;	2004/10/20 07:10
		(position or location or distance) near5 (shaft or spindle or axle	US-PGPUB;	
	;	or axis)) and ((bearing or (roller adj bearing)) near5 error near5	EPO; JPO;	
		vector)	DERWENT; IBM_TDB	,
-	2	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near5	USPAT;	2004/10/20 07:33
		(position or location or distance) near5 (shaft or spindle or axle	US-PGPUB;	
		or axis)) and ((bearing or (roller adj bearing)) with error with vector)	EPO; JPO; DERWENT;	
		1 40001)	IBM_TDB	
-	2	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near5 (shaft	USPAT;	2004/10/20 07:34
		or spindle or axle or axis) with (geometric or geometrical or geometry) with error with vector)	US-PGPUB; EPO; JPO;	
		geometry) with error with vector)	DERWENT;	
			IBM_TDB	
-	4	((measur\$5 or detect\$3 or sens\$3 or determin\$5) near5 (shaft	USPAT; US-PGPUB;	2004/10/20 07:35
		or spindle or axle or axis) with (pointing or indicating or indication) with error with vector)	EPO; JPO;	
			DERWENT;	
		//	IBM_TDB	2004/40/20 20:00
-	97	((measur\$5 or determin\$5 or detect\$3 or sens\$3) near5 (shaft or spindle or axle or axis) near5 (position or location or	USPAT; US-PGPUB;	2004/10/20 08:06
		rotation) near5 (error or fault)) and ((pointing or indicating or	EPO; JPO;	
		indication or index or arrow or needle) near5 (error or fault))	DERWENT;	
	1	4894788.pn.	IBM_TDB USPAT	2004/10/20 08:10
Ļ -		тооттоо.рп.	LOUIAI	2004/10/20 00.10